



What's wrong with this picture?

Worker exposed to fall of more than six feet with no fall protection